

**From:** [Cargill, Dan \(ECY\)](#)  
**To:** [Gay, Megan L.B](#)  
**Cc:** [Thomas, Richard \(ECY\)](#)  
**Subject:** RE: Restoration Areas - Questions  
**Date:** Monday, April 08, 2013 1:14:46 PM  
**Attachments:** [Thales1.pdf](#)  
[Thales2.pdf](#)

---

Megan,

1. Extend this to 5.5 ( I think that's what we agreed to, in order to get the whole Desimone/Boeing/USPS peninsula. I assume the USPS still has a facility there
2. Glad that is resolved
3. Include Thales. This will become one of my poster children for why our databases are not to be relied on. I've attached the entire file I found on the shelf for Thales. I'll see if the Haz Waste Program has anything else in Turbowaste

Dan Cargill  
Department of Ecology  
3190 160<sup>th</sup> Ave SE  
Bellevue, WA 98008-5452  
425-649-7023

*Please note: this email may be considered a record subject to public review.*

 Please don't print this e-mail unless you really need to.

---

**From:** Gay, Megan L.B [mailto:MEGAN.LB.GAY@saic.com]  
**Sent:** Tuesday, April 02, 2013 5:57 PM  
**To:** Thomas, Richard (ECY); Cargill, Dan (ECY)  
**Subject:** RE: Restoration Areas - Questions

Ok, I just double-checked PARIS and determined that Aussie Machine and Thales have CNE certificates, so you can ignore question 2. But please answer questions 1 and 3. ☺

**Megan Buchholz Gay** | SAIC  
Geologist  
Engineering Solutions  
Office: 425.482.3309

Please consider the environment before printing this email.

---

**From:** Gay, Megan L.B  
**Sent:** Tuesday, April 02, 2013 5:48 PM  
**To:** Thomas, Richard (ECY); Cargill, Dan (ECY)  
**Subject:** Restoration Areas - Questions

Hi Rick and Dan,

I have a few questions for the Restoration Areas source control area.

- 1) Why does the source control area end at RM 4.8 West? Should this be extended to RM 5.0 or 5.5?
- 2) According to the Facility/Site Database, one facility in the Hamm Creek SD basin has an

ISGP. It is Aussie Machine, FSID 20863. The permit number is WAR126356 and it was issued on 9/6/2011. The facility does not show up in PARIS and a SWPPP was not requested for the facility as part of the SWPPP project. Is it possible that this was really a Construction SW Permit? Is this an error in the Facility/Site Database?

- 3) Thales Avionics is located on the peninsula of land and would be included in the source control area if it is extended to RM 5.5. The facility also has an ISGP, WAR126494, issued on 12/13/2010. I did not include it in my original request for files because it is outside the source control area if we end at RM 4.8 and didn't show up in initial searches because the coordinates entered in the Facility/Site Database place it in near Green River Community College in Auburn. So the question is...should I include this facility in the Restoration Areas source control area?

Also I wanted to let you know of an error I found in the Facility/Site Database. The (b) (6) property (FSID 64135493) is listed as a UST site. I looked up the property and I doubt that leaded and unleaded gasoline USTs would have been present on this residential property.

The (b) (6) family owned the property occupied by Mike's Aussie Machine (FSID 2334). In an inspection report for Mike's, the (b) (6)'s home address is listed at the bottom. I think this where the error originated. Anyway, I am not including the (b) (6) property in the report. Instead, I am adding the UST information from the (b) (6) property to the discussion regarding Mike's Aussie Machine.

Regards,  
Megan

**Megan Buchholz Gay** | SAIC

Geologist  
Engineering Solutions  
Office: 425.482.3309

18912 North Creek Parkway, #101  
Bothell, WA 98011  
[www.saic.com](http://www.saic.com)

Energy | Environment | National Security | Health | Critical Infrastructure

Please consider the environment before printing this email.

This email and any attachments to it are intended only for the identified recipients. It may contain proprietary or otherwise legally protected information of SAIC or its subsidiary companies. Any unauthorized use or disclosure of this communication is strictly prohibited. If you have received this communication in error, please notify the sender and delete or otherwise destroy the email and all attachments immediately.